DLG Test Report 7270

Gummiwerk KRAIBURG Elastik GmbH & Co. KG **BELMONDO®** Horsewalker GUMMIWERK KRAIBURG ELASTIK BELMONDO® HORSEWALKER Slip Resistance ✓ Slip Resistance DLG Test Report 7270



Overview

A test mark "DLG-APPROVED for individual criteria" is awarded for agricultural products which have successfully fulfilled a scope-reduced usability testing conducted by DLG according to independent and recognised evaluation criteria. The test is intended to highlight particular innovations and key criteria of the test object. The test may



contain criteria from the DLG test scope for overall tests, or focus on other value-determining characteristics and properties of the test subject. The minimum requirements, test conditions and procedures as well as the evaluation bases of the test results will be specified in consultation with an expert group of DLG. They correspond to the recognised rules of technology, as well as scientific and agricultural knowledge and requirements. The successful testing is concluded with the publication of a test report, as well as the awarding of the test mark which is valid for five years from the date of awarding. The test was based on the DLG Testing Framework for elastic flooring for horses, as of August 2019.

Test results

DLG QUALITY PROFILE	Evaluation*
Slip Resistance	
Horse hoof, dry condition	
Horse hoof, wet condition	
Horseshoe, dry condition	
Horseshoe, wet condition	

^{*} DLG Evaluation range:
Single criteria slip resistance: ■ ■ = passed, ■ = failed

Manufacturer and contact information

Manufacturer and Applicant

Gummiwerk KRAIBURG Elastik GmbH & Co. KG Göllstraße 8 D-84529 Tittmoning Germany

Contact

Phone +49 (0)8683 701-527 Fax +49 (0)8683 701-4527 belmondo@kraiburg-elastik.de www.kraiburg-belmondo.de



DLG TestService GmbH Groß-Umstadt location

Max-Eyth-Weg 1 • 64823 Groß-Umstadt • Germany Phone: +49 69 24788-600 • Fax: +49 69 24788-690 Tech@DLG.org • www.DLG.org Download of all
DLG test reports free of charge
at: www.DLG-Test.de